## CONSTRUCTION EQUIPMENT

## [(343446)] LIEBHERR LH60M 124381-1217 - Rear Right Whee

Sample No: LH0289693

=

Oil Type: GEAR OIL SAE 75W90

<b>U</b> Sample Information					
Sample Number		LH0289693	LH0247150	LH0256692	LH0251651
Sample Date		16 Apr 2024	26 Jun 2023	02 Apr 2023	06 Feb 2023
Machine Hours		13245	10141	9107	8526
Oil Hours		0	0	0	0
Oil Changed		N/A	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
Oil Condition					
Visc @ 40°C	cSt	0 106	0 106	0 101	0 101
- <b>1</b>					

Contamination						
Water	%	NEG	NEG	NEG	NEG	
Silicon	ppm	<b>○</b> <1	02	2	02	
Sodium	ppm	6	◯ <1	○ <1	◯ <1	
Potassium	ppm	<b>○</b> <1	0	◯ <1	0 ()	

Õ					
Wea Wea	r Metals				
Iron	ppm	<b>3</b>	04	07	07
Copper	ppm	02	0 4	5	0 4
Lead	ppm	<b>○</b> <1	0	◯ <1	0
Tin	ppm	0 🔘	0	◯ <1	0
Aluminum	ppm	0 🔘	◯ <1	◯ <1	○ <1
Chromium	ppm	0 🔘	0	0	0
Molybdenum	ppm	0 🔘	0	0	0
Nickel	ppm	0 🔘	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	0	0	◯ <1	○ <1
Vanadium	ppm	0	0	0	0

0 **Additives** Calcium ppm 0 16 5 8 🔘 8 🔘 02 Magnesium ppm ○ <1  $\bigcirc 2$ 2 Zinc 013 011 0 14 0 13 ppm Phosphorus ppm 0 1243 0 1278 0 1350 0 1336 Barium 0 0 ppm 0 0 0 319 Boron ◯ 305 ◯ 316 ppm 0 308



## RAM IRON AND METAL

60 Ashwarren Road TORONTO, ON CA M3J 1Z5 Contact: PETER RACCO PETER@RAMIRON.COM T: (416)630-4545 F: (416)630-5258

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	RAMTOR
Unique No:	5762925
Signed:	Wes Davis
Report Date:	17 Apr 2024





٢

Graphs

