LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30 144578-1253 - Swing Drive

Sample No: LH0278716

Visc @

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

Sample Information						
Sample Number	LH0278716	LH0278616	LH0250049			
Sample Date	05 Apr 2024	15 Jan 2024	22 Mar 2023			
Machine Hours	1300	1200	498			
Oil Hours	0	0	0			
Oil Changed	Not Changd	Not Changd	Changed			
Sample Status	NORMAL	NORMAL	NORMAL			
A						

e Status	NORMAL	NORMAL	NORMAL	
Oil Condition				
0 40°C cSt	137	176	180	

Cont	aminatio	n			
Water	%	NEG	NEG	NEG	
Silicon	ppm	0	O 2	O <1	
Sodium	ppm	1	O 1	O <1	
Potassium	ppm	○ <1	O 0	O <1	

Wea	r Metals				
Iron	ppm	27	5 3	O <1	
Copper	ppm	7	O 15	O 0	
Lead	ppm	0	O <1	0	
Tin	ppm	0	O <1	0	
Aluminum	ppm	0 <1	O <1	0	
Chromium	ppm	0	O <1	0	
Molybdenum	ppm	0	0	O 0	
Nickel	ppm	0 <1	O <1	O <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	() <1	0	0	
Vanadium	ppm	0	0	0	

variaulum	ppiii	U	U	U		
Additives						
Calcium	ppm	24	15	○ 18		
Magnesium	ppm	5	O 1	O <1		
Zinc	ppm	11	O 13	4		
Phosphorus	ppm	1551	2237	2401		
Barium	ppm	<1	O <1	0		
Boron	ppm	107	16	O <1		



Industrial Metals 550 Messier St. Winnipeg, MB CA R2J 0G5

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:IND550WINUnique No:5763807Signed:Wes DavisReport Date:22 Apr 2024

CONSTRUCTION EQUIPMENT





Graphs

