LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0286574

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



Conta	mination			
Water	%	NEG	NEG	
Silicon	ppm	10	O 2	
Sodium	ppm	1	O 2	
Potassium	ppm	1	3	
Wear	Metals			

- Wed	r metais				
Iron	ppm	110	O 112	 	
Copper	ppm	11	○ 321	 	
Lead	ppm	() <1	0 8	 	
Tin	ppm	0	O 12	 	
Aluminum	ppm	3	O <1	 	
Chromium	ppm	1	O <1	 	
Molybdenum	ppm	0	0	 	
Nickel	ppm	0	0	 	
Titanium	ppm	<1	0	 	
Silver	ppm	0	0	 	
Manganese	ppm	() <1	4	 	
Vanadium	ppm	0	0	 	

Additives					
Calcium	ppm	22	O 11		
Magnesium	ppm	5	O 1		
Zinc	ppm	26	35		
Phosphorus	ppm	964	O 1261		
Barium	ppm	5	O 2		
Boron	ppm	156	O 5		



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto

steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5763823Signed:Wes DavisReport Date:22 Apr 2024

Contact/Location: Steve Lehto - LIEMIS







Graphs

