LIEBHERR

CONSTRUCTION EQUIPMENT

[MENARD] LIEBHERR HS855 184638 - Right Travel

Sample No: LH0291247
Oil Type: {unknown}

Magnesium

Phosphorus

Zinc

Barium

Boron

ppm

ppm

ppm

ppm

ppm

_				
J Sam	ple Infor	mation		
Sample Number		LH0291247	 	
Sample Date		02 May 2024	 	
Machine Hours		15916	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
	ondition			
Visc @ 40°C	cSt	207	 	
Cont	aminati	on		
Water	%	NEG		
Silicon		○ 12	 	
Sodium	ppm	3	 	
Potassium	ppm	○ <1	 	
	ррпп	0 < 1	 	
Wea	r Metals	.		
Iron	ppm	9 1	 	
Copper	ppm	07	 	
Lead	ppm	0	 	
Tin	ppm	0 0	 	
Aluminum	ppm	2	 	
Chromium	ppm	0 <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
Addi	itives	11		
Jaioluiii	ppin	- 11		



LIEBHERR CANADA LTD.
1015 SUTTON DRIVE
BURLINGTON, ON
CA L7L 5Z8
Contact: Steve Lehto
steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 220 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5775083Signed:Kevin MarsonReport Date:07 May 2024

Contact/Location: Steve Lehto - LIEMIS

<1

7

0

293

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

