LIEBHERR





LIEBHERR L580 071613-1760 - Rear Right Wheel Hub

Sample No: LH0292400

Oil Type: LIEBHERR GEAR BASIC 90 LS

<u> </u>						
Sample Information						
Sample Number	LH0292400	LH0277089				
Sample Date	22 Jun 2024	14 Oct 2023				
Machine Hours	2202	1054				
Oil Hours	0	0				
Oil Changed	Changed	Changed				
Sample Status	NORMAL	NORMAL				
A						



BIRCH HILL CONSTRUCTION 11 MCELROY ST. MONCTON, NB

CA E1C 9T2

Contact: Service Manager

Т	:
F	:

0	Oil Co	ndition			
/isc @ 4	40°C	cSt	186	195	
- 1					

Conta	mination			
Water	%	NEG	NEG	
Silicon	ppm	10	20	
Sodium	ppm	3	6	
Potassium	ppm	0 <1	2	

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

(O) Was				
Wed	ar Metal:	S		
Iron	ppm	() 101	O 177	
Copper	ppm	46	O 140	
Lead	ppm	() <1	4	
Tin	ppm	4	O 7	
Aluminum	ppm	0 <1	1	
Chromium	ppm	1	O 2	
Molybdenum	ppm	0	0	
Nickel	ppm	0 <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	19	43	
Vanadium	ppm	0	0	
-				

variaululli	ppiii	U	U	
Addit	ives			
Calcium	ppm	6	O 10	
Magnesium	ppm	○ <1	1	
Zinc	ppm	40	66	
Phosphorus	ppm	2195	O 2254	
Barium	ppm	() <1	O <1	
Boron	ppm	0 <1	O 2	

Depot:BIRMONUnique No:5802202Signed:Kevin MarsonReport Date:02 Jul 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

