

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [NACG] LIEBHERR LRH100 115117 - Right Track Drive

Sample No: LH0292293

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90



#### Sample Information

Sample Number	LH0292293	LH0070684	---	---
Sample Date	04 Jul 2024	01 Mar 2013	---	---
Machine Hours	349	872	---	---
Oil Hours	0	0	---	---
Oil Changed	Not Chngd	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

**LIEBHERR CANADA LTD.**  
 1015 SUTTON DRIVE  
 BURLINGTON, ON  
 CA L7L 5Z8  
 Contact: Steve Lehto  
 steve.lehto@liebherr.com  
 T: (905)319-9222  
 F: (905)319-6617



#### Oil Condition

Visc @ 40°C	cSt	● 126	● 191	---	---
-------------	-----	-------	-------	-----	-----



#### Contamination

Water	%	NEG	NEG	---	---
Silicon	ppm	● 40	● 77	---	---
Sodium	ppm	● 2	● 11	---	---
Potassium	ppm	● 5	● 5	---	---



#### Wear Metals

Iron	ppm	● 78	● 112	---	---
Copper	ppm	● 4	● 5	---	---
Lead	ppm	● 0	● <1	---	---
Tin	ppm	● 0	● <1	---	---
Aluminum	ppm	● 12	● 7	---	---
Chromium	ppm	● 2	● 2	---	---
Molybdenum	ppm	● 0	● <1	---	---
Nickel	ppm	● <1	<1	---	---
Titanium	ppm	<1	<1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	● 1	4	---	---
Vanadium	ppm	0	0	---	---



#### Additives

Calcium	ppm	● 20	● 13	---	---
Magnesium	ppm	● 4	● 3	---	---
Zinc	ppm	● 11	● 112	---	---
Phosphorus	ppm	498	● 1120	---	---
Barium	ppm	● <1	● 2	---	---
Boron	ppm	25	● 2	---	---

#### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS  
 Unique No: 5812336  
 Signed: Wes Davis  
 Report Date: 09 Jul 2024



### Graphs

