LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L586 74609 - Rear Differential

Sample No: LH0295162

Oil Type: LIEBHERR GEAR BASIC 90 LS

5				
U Sam	ple Info	rmation		
Sample Number		LH0295162	 	
Sample Date		07 Jul 2024	 	
Machine Hours		3024	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
A				
Oilc	ondition			
Visc @ 40°C	cSt	180	 	
Cont	aminati	on		
Water	%	NEG	 	
Silicon	ppm	7	 	
Sodium	ppm	3	 	
Potassium	ppm	0 <1	 	
(O) Wes	ır Metal:	•		
Iron	ppm	O 150	 	
Copper	ppm	○ 82	 	
Lead Tin	ppm	01	 	
	ppm	O 4	 	
Aluminum Chromium	ppm	0 <1	 	
	ppm	○ <1	 	
Molybdenum Nickel	ppm	○ 0 ○ <1	 	
Titanium	ppm			
Silver	ppm	0	 	
Manganese	ppm	7	 	
Vanadium	ppm	0	 	
	ρριτι	U	 	
Addi) _# 0		 	
Addi	itives			
Calcium	ppm	4	 	
Magnesium	ppm	1	 	
Zinc	ppm	52	 	
- ·		0		



MODERN CONSTRUCTION (1983) LTD.

364 BRIGGS CROSS ROAD STILESVILLE, NB CA E1G 3G3 Contact: Blaine Cail

blaine.cail@moderngroup.ca

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:MODSTIUnique No:5813235Signed:Wes DavisReport Date:12 Jul 2024

Contact/Location: Blaine Cail - MODSTI

2259

<1</p>

() <1

Phosphorus

Barium

Boron

ppm

ppm

ppm

LIEBHERR







Graphs

