LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 073621-1760 - Diesel Engine

Sample No: LH0283335

Oil Type: SHELL ROTELLA T6 0W40

_ sam	pie intol	rmation		
Sample Number		LH0283335	 	
Sample Date		24 Jun 2024	 	
Machine Hours		1740	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
Oil C	ondition	1		
Visc @ 100°C	cSt	13.9	 	
Oxidation (PA)	%	67	 	
Cont	aminati	on		
	<mark>aminati</mark> %	on NEG	 	
Water			 	
Water Soot %	%	NEG		
Water Soot % Nitration (PA)	%	NEG	 	
Water Soot % Nitration (PA) Sulfation (PA)	% % %	NEG 0 67	 	
Water Soot % Nitration (PA) Sulfation (PA) Glycol	% % %	NEG	 	
Water Soot % Nitration (PA) Sulfation (PA) Glycol Fuel	% % % %	NEG 0 67 48 0 0.0	 	
Water Soot % Nitration (PA) Sulfation (PA) Glycol Fuel Silicon Sodium	% % % % % %	NEG 0 67 48 0 0.0 <1.0	 	

Wed Wed	ır Metals			
Iron	ppm	4	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	3	 	
Nickel	ppm	() <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

	le le			
Add	E0_0			
	litives			
Calcium	ppm	2027	 	
Magnesium	ppm	11	 	
Zinc	ppm	1103	 	
Phosphorus	ppm	976	 	
Barium	ppm	<1	 	
Boron	ppm	30	 	
DOTOTI	ppiii	000		



HUBERT & FILS
474 ROUTE 105
BOIS-FRANC, QC
CA J9E 3A9
Contact: Eric Brisebois
ericbrisebois99@gmail.com
T.

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: HUBBOI
Unique No: 5814176
Signed: Wes Davis
Report Date: 18 Jul 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

