# LIEBHERR

# **CONSTRUCTION EQUIPMENT**

## LIEBHERR LH3OM 135986 - Splitter Box

Sample No: LH

Oil Type: GEAR OIL SAE 80W90

ā						
Sample Information						
Sample Number	LH	LH	LH0278481			
Sample Date	04 Jul 2024	07 May 2024	22 Dec 2023			
Machine Hours	5083	4737	3966			
Oil Hours	0	0	0			
Oil Changed	Changed	Changed	Changed			
Sample Status	NORMAL	NORMAL	NORMAL			
<b>A</b>						

Sample	Status		NORWAL	NORIVIAL	NORWAL	
0	Oil Co	ndition				
Visc @	40°C	cSt	<b>172</b>	O 177	O 177	
-4						

Contamination	
Water % NEG NEG	
Silicon	
Sodium	
Potassium ppm	

Wea	r Metals				
Iron	ppm	<b>5</b>	<b>8</b>	<b>8</b>	
Copper	ppm	<b>0</b> <1	<b>1</b>	<b></b> <1	
Lead	ppm	<b>0</b>	O <1	O 0	
Tin	ppm	<b>0</b>	0	O 0	
Aluminum	ppm	<b>0</b> <1	O <1	<b>1</b>	
Chromium	ppm	<b>0</b>	<b>0</b>	<b>0</b>	
Molybdenum	ppm	<b>0</b>	0	O 0	
Nickel	ppm	<b>O</b> <1	0	O <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	<b>0</b> 0	O 0	O 0	
Vanadium	ppm	0	0	0	

Add	litives				
Calcium	ppm	<b>39</b>	<b>3</b> 7	○ 38	
Magnesium	ppm	<b>○</b> <1	O 2	O 2	
Zinc	ppm	<b>28</b>	O 25	<b>24</b>	
Phosphorus	ppm	<b>2311</b>	O 2207	O 2237	
Barium	ppm	<b>0</b>	O	O 0	
Boron	ppm	<b>2</b>	<b>4</b>	<b>5</b>	



#### Industrial Metals 550 Messier St. Winnipeg, MB CA R2J 0G5

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:IND550WINUnique No:5814286Signed:Wes DavisReport Date:18 Jul 2024

Submitted By: Vincent Blanchette

**CONSTRUCTION EQUIPMENT** 





### **Graphs**

