LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR R922 54275 - Right Final Drive

Sample No: LH0280967

Aluminum

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Molybdenum

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

38 ② 2

0

01

2

2

<1

_									
Sample Information									
Sample Number		LH0280967	LH0238612						
Sample Date		06 Jun 2024	22 Feb 2023						
Machine Hours		3000	518						
Oil Hours		0	0						
Oil Changed		Changed	Changed						
Sample Status		NORMAL	NORMAL						
Oil Condition									
Visc @ 40°C	cSt	91.3	195						
Contamination									
Water	%	NEG	NEG						
Silicon	ppm	112	O 2						
Sodium	ppm	9	7						
Potassium	ppm	11	O 2						
Wear Metals									
Iron	ppm	200	4 3						
Copper	ppm	○ <1	O 0						
Lead	ppm	0	O 0						
Tin	ppm	0	0						



Liebherr Canada

140 - 21320 Gordon Way Richmond, BC CA V6W 1J8 Contact: Kevin Steer kevin.steer@liebherr.com

T:

F: (604)270-3254

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

	1-1-								
Additives									
Calcium	ppm	24	O 12						
Magnesium	ppm	12	O <1						
Zinc	ppm	12	1 3						
Phosphorus	ppm	1250	1389						
Barium	ppm	1	10						
Boron	ppm	277	4						

Depot: LIERIC
Unique No: 5814305
Signed: Kevin Marson
Report Date: 19 Jul 2024

Contact/Location: Kevin Steer - LIERIC

LIEBHERR







Graphs

