LIEBHERR

CONSTRUCTION EQUIPMENT



[(366422)] LIEBHERR LH30M 135772-1253 - Front Left Wheel

Sample No: LH0223393

Oil Type: LIEBHERR GEAR BASIC 90 LS

5					
U San	nple Infor	mation			
Sample Numbe	r	LH0223393	LH	LH0223412	
Sample Date		12 Jul 2024	03 May 2024	13 Oct 2023	
Machine Hours		7083	6597	4937	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
Oil	Condition	ı			
Visc @ 40°C	cSt	133	79.5	94.5	
**					
Con	taminati	on			
Water	%	NEG	NEG	NEG	

Conta	mination				
Water	%	NEG	NEG	NEG	
Silicon	ppm	41	O 21	49	
Sodium	ppm	18	5	1 4	
Potassium	ppm	4	O <1	4	
Wear	Metals				

Wed	ır Metals				
Iron	ppm	373	O 227	253	
Copper	ppm	4	6	O 2	
Lead	ppm	0	O 0	<1	
Tin	ppm	0	0	0	
Aluminum	ppm	6	O 2	O 11	
Chromium	ppm	2	O <1	O 1	
Molybdenum	ppm	0	O 0	O	
Nickel	ppm	 <1	O 0	O <1	
Titanium	ppm	<1	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	4	O 2	2	
Vanadium	ppm	0	0	0	

Variadiani	ppiii	· ·	O O	0			
Additives							
Calcium	ppm	312	60	107			
Magnesium	ppm	9	O 4	O 11			
Zinc	ppm	65	73	17			
Phosphorus	ppm	1873	957	O 1034			
Barium	ppm	2	O <1	3			
Boron	ppm	92	33	O 122			



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. Viscosity of sample indicates oil is within SAE 90 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5814316Signed:Kevin MarsonReport Date:19 Jul 2024





Graphs

