LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0269689

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



 \bigcirc <1

6

 \bigcirc 0

331

1332

02

9

 \bigcirc 0

118

302



LIEBHERR CANADA LTD.

10374 267 ST. ACHESON, AB CA T7X 6A2

Contact: Dustin Fluet dustin.fluet@liebherr.com

T: (780)962-6088 F: (780)962-6799

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIESPRUnique No:5814341Signed:Wes DavisReport Date:18 Jul 2024

Contact/Location: Dustin Fluet - LIESPR

1

8

 \bigcirc 0

301

1316

ppm

ppm

ppm

ppm

ppm

Magnesium

Phosphorus

Zinc

Barium


Boron

CONSTRUCTION EQUIPMENT





Graphs



Report Id: LIESPR [WCAMIS] 02648789 (Generated: 07/18/2024 15:39:45) Rev: 1