# LIEBHERR

### **CONSTRUCTION EQUIPMENT**

### 054454-194 - Rear Left Wheel Hub

Sample No: LHMC123425

Oil Type: LIEBHERR GEAR BASIC 90 LS





CONTAMINATION							
Water	%	NEG					
Silicon	ppm	<b>2</b>		***			
Sodium	ppm	<b>2</b>					
Potassium	ppm	<b>2</b>					

WEA	R METAL	.S		
Iron	ppm	<b>42</b>	 	
Copper	ppm	<b>12</b>	 	
Lead	ppm	<b>○</b> <1	 	
Tin	ppm	<b>O</b> <1	 	
Aluminum	ppm	<b>()</b> <1	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	<b>()</b> <1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	0	 	

Vanadium	ppm	0				
ADDITIVES						
Calcium	ppm	<b>0</b> 7				
Magnesium	ppm	<b>0</b>				
Zinc	ppm	<b>18</b>				
Phosphorus	ppm	<b>1497</b>				
Barium	ppm	<b>109</b>				
Boron	ppm	<b>163</b>				



#### **UNITED STATES GYPSUM**

301 RILEY RD EAST CHICAGO, IN US 43612

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:UNIEASLHUnique No:8883920Signed:Don BaldridgeReport Date:16 Jan 2020

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

