LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 145582-1216 - Front Left Wheel Hub

Sample No: LH0243265

Oil Type: LIEBHERR GEAR BASIC 90 LS

_				
U SAN	APLE INF	ORMATION		
Sample Number		LH0243265	LH0243205	
Sample Date		15 Jun 2023	15 Mar 2023	
Machine Hours		1005	461	
Oil Hours		0	461	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL	CONDITION	ON		
Visc @ 40°C	cSt	141	141	
CON	ITAMIN/	ATION		
Silicon	ppm	12	O 13	

CONT	AMINATIO	ON		
Silicon	ppm	12	1 3	
Sodium	ppm	7	O 11	
Potassium	ppm	6	4	
WEA	R METALS			

W VY EA	R MEIALS			
Iron	ppm	42	O 45	
Copper	ppm	14	9	
Lead	ppm	1	0	
Tin	ppm	() <1	0	
Aluminum	ppm	4	0 1	
Chromium	ppm	O <1	O <1	
Molybdenum	ppm	1	O 1	
Nickel	ppm	() <1	0	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	4	4	
Vanadium	ppm	0	<1	

ADD	ITIVES			
Calcium	ppm	70	O 64	
Magnesium	ppm	6	O 5	
Zinc	ppm	25	16	
Phosphorus	ppm	1642	O 1506	
Barium	ppm	0	O 0	
Boron	ppm	54	O 72	



RECO EQUIPMENT INC

10461 GRAND RIVER RD BRIGHTON, MI US 48116

Contact: MATT VISEL
MVISEL@RECOEQUIP.COM

T: (810)299-1731

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RECBRILHUnique No:10535226Signed:Jonathan HesterReport Date:30 Jun 2023

CONSTRUCTION EQUIPMENT





GRAPHS

