## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

#### LIEBHERR L586 1761-66584 - Splitter Box

Sample No: LH05893047
Oil Type: NOT GIVEN





#### OZINGA MATERIALS

11701 S TORRENCE AVE CHICAGO, IL

US 60617

Contact: RYAN DEWINDT ryandewindt@ozinga.com

T: (708)243-6910 F: (773)375-7226

_									
SAMPLEINFORMATION									
Sample Number		LH05893047							
Sample Date		10 Jun 2023							
Machine Hours		2523							
Oil Hours		0							
Oil Changed		Changed							
Sample Status		NORMAL							

#### OIL CONDITION

### CONTAMINATION

 Silicon
 ppm
 1
 -- -- -- 

 Sodium
 ppm
 2
 -- -- -- 

 Potassium
 ppm
 0
 -- -- --

## 0

#### **WEAR METALS**

Iron ppm **51** Copper **2** ppm Lead 0 ppm Tin **0** ppm Aluminum ppm 0 <1 Chromium ppm 0 <1 Molybdenum ppm 5 Nickel  $\bigcirc$  0 ppm Titanium ppm 0 Silver ppm 0 Manganese <1 ppm Vanadium ppm



#### **ADDITIVES**

Calcium	ppm	46					
Magnesium	ppm	10					
Zinc	ppm	34					
Phosphorus	ppm	2045					
Barium	ppm	0					
Boron	ppm	363					

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: CHICHILH
Unique No: 10548857
Signed: Don Baldridge
Report Date: 11 Jul 2023

# CONSTRUCTION EQUIPMENT





#### **GRAPHS**

