LIEBHERR

CONSTRUCTION EQUIPMENT



NOT GIVEN LH0220959 (S/N NO INFO ON SIF/BOTTLE) - Diese

Sample No: LH0220959

Oil Type: LIEBHERR MOTOROIL 5W30

5						
SAMPLEINFORMATION						
Sample Number		LH0220959				
Sample Date		23 Aug 2023				
Machine Hours		0				
Oil Hours		0				
Oil Changed		N/A				
Sample Status		NORMAL				
OIL CONDITION						
Visc @ 100°C	cSt	12.2				
Base Number (BN)	mg KOH/g	○ 8.2				
Oxidation (PA)	%	187				

**					
CONTAMINATION					
Soot %	%	0.1			
Nitration (PA)	%	68			
Sulfation (PA)	%	106			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	16			
Sodium	ppm	2			
Potassium	ppm	2			
.adda.					

WEA	R METALS			
Iron	ppm	4	 	
Copper	ppm	13	 	
Lead	ppm	○ <1	 	
Tin	ppm	○ <1	 	
Aluminum	ppm	6	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	46	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	1388				
Magnesium	ppm	940				
Zinc	ppm	911				
Phosphorus	ppm	773				
Barium	ppm	44				
Boron	ppm	169				



LIEBHERR EQUIPMENT SOURCE

4100 CHESTNUT AVENUE NEWPORT NEWS, VA

US 23607

Contact: LUKE APPLEBY Lucas.Appleby@liebherr.com

Т:

F: (757)298-8700

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:LIEBHERRUSUnique No:10619304Signed:Don BaldridgeReport Date:26 Aug 2023

LIEBHERR







GRAPHS

