LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 1216-109503 - Front Left Wheel Hub

Sample No: LHMC162792

_

Magnesium

Phosphorus

Zinc

Barium

Boron

ppm

ppm

ppm

ppm

ppm

Oil Type: GEAR OIL SAE 75W90

Sample Number		LHMC162792	LHMC162803	
Sample Date		15 Sep 2023	23 Mar 2023	
Machine Hours		6608	5400	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
<u> </u>				
OII (CONDITION	ON		
/isc @ 40°C	cSt	O 144	O 147	
71SC @ 40 C	CSI	144	0 147	
CON	ITAMIN	ATION		
Silicon	ppm	27	3 7	
Sodium	ppm	16	O 13	
Potassium	ppm	4	O 1	
-				
◎ WE	AR META	LS		
Iron	ppm	○ 357	O 362	
Copper	ppm	○ 65	O 73	
Lead	ppm	0	00	
Tin	ppm	0	00	
Aluminum	ppm	O 2	05	
Chromium	ppm	○ <1	0 1	
Molybdenum	ppm	00	O 1	
Vickel	ppm	0	00	
Titanium	ppm	0	00	
Silver	ppm	0	00	
Manganese	ppm	6	O 6	
Vanadium	ppm	0	0	
MIII.				
ADD	ITIVES			
	HILLED			
o	10 10 100	184	O 196	
Calcium	ppm	0 104	0 190	

93

0

2068



AHLSTROM-MUNKSJO NA SPECIALTY

PO BOX 600 KAUKAUNA, WI US 54130

Contact: JOE SEITZ

joe.seiltz@ahlstrom-munksjo.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:AHLKAUUnique No:10660484Signed:Don BaldridgeReport Date:26 Sep 2023

6

90

0

<1</p>

1980

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

