

## LIEBHERR LH50 145582-1216 - Rear Differential

Sample No: LH0268529

٥

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

**ADDITIVES** 

ppm

ppm

ppm

ppm

ppm

ppm

Oil Type: LIEBHERR GEAR BASIC 90 LS

## SAMPLE INFORMATION

Sample Number	LH0268529	LH0243272	LH0243210	
Sample Date	19 Sep 2023	15 Jun 2023	15 Mar 2023	
Machine Hours	1633	1005	461	
Oil Hours	1633	0	461	
Oil Changed	Not Changd	N/A	Not Changd	
Sample Status	NORMAL	NORMAL	NORMAL	
OIL CONDITION				
Visc @ 40°C cSt	0 155	0 147	0 152	

	TAMIN/	ATION			
Silicon	ppm	07	2	07	
Sodium	ppm	01	○ 5	03	
Potassium	ppm	01	2	0	

~		<u> </u>			
WEA	R META	LS			
Iron	ppm	22	6	0 17	
Copper	ppm	0 18	06	6	
Lead	ppm	<mark></mark> <1	○ <1	0	
Tin	ppm	0 (	○ <1	0	
Aluminum	ppm	◯ <1	2	0	
Chromium	ppm	<mark></mark> <1	○ <1	○ <1	
Molybdenum	ppm	04	○ <1	0 4	
Nickel	ppm	0 (	○ <1	0	
Titanium	ppm	0	<1	<1	
Silver	ppm	0	0	0	
Manganese	ppm	<mark></mark> <1	01	2	
Vanadium	ppm	0	0	<1	

06

6

03

0 97

0 111

0 1548

0 190

04

24

0

0 10

0 1438



#### **RECO EQUIPMENT INC**

10461 GRAND RIVER RD BRIGHTON, MI US 48116 Contact: MATT VISEL MVISEL@RECOEQUIP.COM T: (810)299-1731 F:

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	RECBRILH
Unique No:	10669690
Signed:	Don Baldridge
Report Date:	29 Sep 2023

0 170

01

0 36

0

05

0 1445

Contact/Location: MATT VISEL - RECBRILH







# **GRAPHS**

