LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 066006-1760 - Splitter Box

Sample No: LH0262526

Oil Type: GEAR OIL SAE 80W90



Sample	Status		NUNWAL	 	
0	OIL CO	NDITION			
Visc @	40°C	cSt	133	 	

CON	CONTAMINATION							
Silicon	ppm	2						
Sodium	ppm	2						
Potassium	ppm	<1						

WEAR METALS					
Iron	ppm	76			
Copper	ppm	0 <1			
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	() <1			
Chromium	ppm	0 <1			
Molybdenum	ppm	0			
Nickel	ppm	() <1			
Titanium	ppm	0			
Silver	ppm	<1			
Manganese	ppm	1			
Vanadium	ppm	0			

		ADDITIVES						
pm	5							
ppm	0							
ppm	0							
ppm	1114							
ppm	0							
ppm	220							
	pm pm pm pm	pm 0 0 pm 0 1114 pm 0 0	pm 0 pm 0 pm 0 1114 pm 0 0	pm 0 pm 0 1114 pm 0 0				



MR BULTS INC 2627 E 139TH ST BURNHAM, IL US 60633

Contact: SERVICE MANAGER

T: (708)868-0059 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: MRBBURLH
Unique No: 10701168
Signed: Don Baldridge
Report Date: 21 Oct 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

