## LIEBHERR

## **CONSTRUCTION EQUIPMENT**

### LIEBHERR LH50 1216-131191 - Rear Differential

Sample No: LH0227816

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION							
Sample Number	LH0227816	LH0227804					
Sample Date	12 Oct 2023	08 Feb 2023					
Machine Hours	1905	1117					
Oil Hours	0	0					
Oil Changed	Changed	Changed					
Sample Status	NORMAL	NORMAL					
<b>A</b>							

Jampio	Otatao		HOIMAL	1401111111		
	OIL CO	NDITION				ı
/isc @	40°C	cSt	<b>129</b>	<b>145</b>	 	١
_						

CONT	'AMINATIO	ON		
Silicon	ppm	<b>2</b>	<b>4</b>	 
Sodium	ppm	<b>2</b>	O 0	 
Potassium	ppm	<b>1</b>	<b>4</b>	 

WEA	R METALS			
Iron	ppm	<b>22</b>	<b>3</b> 5	 
Copper	ppm	<b>4</b>	<b>4</b>	 
Lead	ppm	<b>0</b>	0	 
Tin	ppm	<b>0</b>	0	 
Aluminum	ppm	<b>0</b> <1	O 1	 
Chromium	ppm	<b>0</b>	O <1	 
Molybdenum	ppm	<b>○</b> <1	O <1	 
Nickel	ppm	<b>0</b>	0	 
Titanium	ppm	<1	0	 
Silver	ppm	0	0	 
Manganese	ppm	<b>0</b> <1	O 1	 
Vanadium	ppm	0	0	 

ADDITIVES								
Calcium	ppm	<b>34</b>	<b>48</b>					
Magnesium	ppm	<b>5</b>	<b>3</b>					
Zinc	ppm	<b>20</b>	O 26					
Phosphorus	ppm	<b>833</b>	724					
Barium	ppm	<b>0</b>	O <1					
Boron	ppm	<b>2</b>	<b>5</b>					



#### KOPPERS RECOVERY RESOURCES

17961 US HIGHWAY 41 L`ANSE, MI

L`ANSE, M US 49946

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:KOPLANUnique No:10701544Signed:Doug BogartReport Date:20 Oct 2023

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

