

LIEBHERR LH50 142548-1216 - Front Left Wheel Hub

Sample No: LH0272486

- **1**


Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0272486	LH0243155				
Sample Date	30 Oct 2023	11 Jan 2023				
Machine Hours	1993	473				
Oil Hours	0	0				
Oil Changed	Changed	Changed				
Sample Status	NORMAL	NORMAL				
OIL CONDITION						
Visc @ 40°C cSt	123	0 162				

	ITAMINAT	ION			
Silicon	ppm	02	0 15	 	
Sodium	ppm	04	0 4	 	
Potassium	ppm	◯ <1	0 2	 	

-		•	Ū	
	AR METAL	F		
	AR MEIAL	3		
Iron	ppm	0 39	68	
Copper	ppm	0 16	0 19	
Lead	ppm	0	◯ <1	
Tin	ppm	0 (○ <1	
Aluminum	ppm	0	2	
Chromium	ppm	0	○ <1	
Molybdenum	ppm	0	0 2	
Nickel	ppm	0	○ <1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	01	03	
Vanadium	maa	0	0	





AMERICAN STATE EQUIPMENT CO.

2400 NORTH 14TH AVENUE WAUSAU, WI US 54401 Contact: CHRIS BARTNIK cbartnik@amstate.com T: (715)675-6900 F: (715)675-9748

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LEC0008
Unique No:	10728449
Signed:	Sean Felton
Report Date:	08 Nov 2023







