# LIEBHERR

# **CONSTRUCTION EQUIPMENT**

## LIEBHERR R926 1715-51969 - Splitter Box

Sample No: LH0202120

Oil Type: GEAR OIL SAE 80W90

<u> </u>					
SAM	<b>PLE INFOR</b>	MATION			
Sample Number		LH0202120	LH05635183	LH0202111	
Sample Date		02 Nov 2023	05 Sep 2022	27 Oct 2021	
Machine Hours		2002	1010	508	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Changed	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
<u> </u>					
OILC	ONDITION				
Visc @ 40°C	cSt	<b>136</b>	<b>183</b>	O 195	
-4					
CON	TAMINATI	ON			
Silicon	ppm	<b>2</b>	0 2	O 2	
Sodium	ppm	<b>2</b>	0 1	<b>O</b> 4	
Potassium	ppm	<b>○</b> <1	0	<1	
(Ö)					
WEA	R METALS	3			
Iron	ppm	<b>21</b>	O 13	O 15	
Copper	ppm	<b>○</b> <1	O 1	O 1	
Lead	ppm	<b>0</b>	O 0	O 0	
Tin	ppm	<b>0</b>	<1	<b>0</b>	
Aluminum	ppm	<b>0</b>	O 1	<1 <1	
Chromium	ppm	<b>0</b>	O <1	O <1	
Molybdenum	ppm	<b>3</b>	0	0	
Nickel	ppm	<b>0</b>	O <1	O <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	<1	0	
Manganese	ppm	<b>0</b>	<1	<1	
Vanadium	ppm	0	0	<1	
ADD	ITIVES				
Calcium	ppm	<b>92</b>	23	18	
Magnesium	ppm	<b>26</b>	1	7	
Zinc	ppm	<b>54</b>	17	19	
Phosphorus	ppm	O 1181	1831	1396	
Barium	ppm	<b>0</b> 1	0	<1	
_		<u> </u>			



#### **DIEHL AND NUEMAIER**

5466 NORWAY GROVE SCHOOL RD

DE FOREST, WI US 53532

Contact: ELLIOT DIEHL diehlneumaier@yahoo.com

T: (608)846-4824 F: (608)846-2077

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: DIEDEF
Unique No: 10740340
Signed: Don Baldridge
Report Date: 15 Nov 2023

**21** 

ppm

Boron





## **GRAPHS**

