
## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

#### LIEBHERR LH30M 1253-133792 - Transmission

Sample No: LH0272883
Oil Type: SAE 10W40



OIL CO	ONDITION			
Visc @ 40°C	cSt	<b>109</b>	<b>54.6</b>	 
-4				

CONTAMINATION							
Water	%	NEG	NEG				
Silicon	ppm	<b>8</b>	O 7		***		
Sodium	ppm	<b>0</b>	<b>20</b>				
Potassium	ppm	<b>○</b> <1	0 2				

<b>(</b> )		_		
WEA	R METAL	S		
Iron	ppm	<b>5</b>	O 42	 
Copper	ppm	<b>5</b>	O 87	 
Lead	ppm	<b>0</b>	O <1	 
Tin	ppm	<b>0</b>	0 1	 
Aluminum	ppm	<b>4</b>	<b>6</b>	 
Chromium	ppm	<b>0</b>	O <1	 
Molybdenum	ppm	<b>80</b>	45	 
Nickel	ppm	<b></b> <1	0	 
Titanium	ppm	<b></b> <1	<1	 
Silver	ppm	<1	0	 
Manganese	ppm	<b></b> <1	16	 
Vanadium	ppm	<1	0	 

variaulum	ppiii	< 1	U			
ADDITIVES						
Calcium	ppm	<b>2100</b>	2865			
Magnesium	ppm	<b>46</b>	50			
Zinc	ppm	<b>1237</b>	1206			
Phosphorus	ppm	<b>1072</b>	1059			
Barium	ppm	<b>0</b>	0			
Boron	ppm	<b>94</b>	50			



### **C&C SCRAP IRON AND METALS INC** P.O. BOX 549

P.O. BOX 549 KING MOUNTAIN, NC US 28086

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:CCSKINUnique No:10803078Signed:Don BaldridgeReport Date:24 Dec 2023

# CONSTRUCTION EQUIPMENT





#### **GRAPHS**

