

# LIEBHERR R936LC 047 223-2149 - Diesel Fuel

Sample No: LHMC93456

Oil Type: NOT GIVEN

## SAMPLE INFORMATION

Sample Number	LHMC93456	 	
Sample Date	10 Dec 2023	 	
Machine Hours	4596	 	
Sample Status	NORMAL	 	

<b>FUEL</b> O	ONDITION	1		
Sulfur	ppm	0	 	
Visc @ 40°C	cSt	0 2.6	 	

	NTAMINA	TION		
Water	%	0.003	 	
Lead	ppm	0 🔘	 	
Nickel	ppm	0	 	
Aluminum	ppm	0 🔘	 	
Vanadium	ppm	0	 	
Silicon	ppm	0	 	





#### **BANE MACHINERY INC**

2449 MANANA DR DALLAS, TX US 75220 Contact: BOBBIE WADLEY bwadley@banemachinery.com T: (214)352-2468 F:

## Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time.All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot:BANDALUnique No:10804851Signed:Jonathan HesterReport Date:29 Dec 2023



 $\odot$ 

GRAPHS



## Pensky-Martens Flash Point (°C)

1	0-	ľ	1			-	 				 	 	 -							 	-					 -		
	8-																											
	6.																											
	4-																											
د u	2.		i																									
eratur	0.																											
2	2																											
-	4.																											
-	6																											
-	8 -																											
-1	0		Ļ																					_				
		0001	0/72																									
			Lec L																									