LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH60 1217-146108 - Front Left Wheel Hub

Sample No: LH0269009

Oil Type: DURALENE Posi-Traction 80W90

<u> </u>						
SAMI	PLE INFOR	MATION				
Sample Number		LH0269009				
Sample Date		04 Dec 2023				
Machine Hours		1154				
Oil Hours		0				
Oil Changed		Not Changd				
Sample Status		NORMAL				
OIL CONDITION						
Visc @ 40°C	cSt	131				

CONTAMINATION						
Water	%	NEG				
Silicon	ppm	2				
Sodium	ppm	3				
Potassium	ppm	3				

(O) WE				
₩ WEA	IR META	LS		
Iron	ppm	51	 	
Copper	ppm	6	 	
Lead	ppm	() <1	 	
Tin	ppm	0 <1	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0 <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	

vanadium	ppm	U				
ADDITIVES						
Calcium	ppm	103				
Magnesium	ppm	14				
Zinc	ppm	57				
Phosphorus	ppm	1653				
Barium	ppm	3				
Boron	ppm	167				



CONSERVIT INC. PO BOX 1517 HAGERSTOWN, MD US 21740 Contact: DON LONG

Contact: DON LONG dlong@conservit.biz T: (301)791-0100 F: (301)739-8548

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:CONHAGUnique No:10809085Signed:Don BaldridgeReport Date:03 Jan 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

