

LIEBHERR LH30M 1253-123497 - Front Left Wheel Hub

Sample No: LH0272903

ø

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0272903	LH0212311	
Sample Date	11 Jan 2024	30 Dec 2021	
Machine Hours	4554	981	
Oil Hours	0	0	
Oil Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	

OIL CONDITION Visc @ 40°C cSt 122 107 --

11					
Water	%	NEG	NEG		
Silicon	ppm	0 2	0 6		
Sodium	ppm	○ <1	6		
Potassium	ppm	○ <1	0		

Ä				
WEA	R METAL	S		
Iron	ppm	0 34	58	
Copper	ppm	0 5	0 16	
Lead	ppm	0	0 <1	
Tin	ppm	0	<1	
Aluminum	ppm	2	0	
Chromium	ppm	○ <1	○ <1	
Molybdenum	ppm	0 🔘	○ <1	
Nickel	ppm	0 🔘	0	
Titanium	ppm	0	<1	
Silver	ppm	0	<1	
Manganese	ppm	0	0 1	
Vanadium	ppm	0	0	

0 495

293

0 542

0

0 69

02

Diagnosis Bosample at

US 29303

т:

F:

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	SF
Unique No:	10
Signed:	We
Report Date:	18

PASPALH 0834556 /es Davis 8 Jan 2024

98

01

03

03

01

0 320

Submitted By: ?



SPARTAN RECYCLING 3071 HOWARD ST SPARTANBURG, SC

Contact: SERVICE MANAGER





GRAPHS

Ö

Ferrous Alloys

