

# LIEBHERR LH50M 145108-1216 - Rear Left Wheel Hub

Sample No: LH0272118

Oil Type: LIEBHERR GEAR BASIC 90 LS

# **SAMPLE INFORMATION**

Sample Number	LH0272118	 	
Sample Date	21 Dec 2023	 	
Machine Hours	1655	 	
Oil Hours	1655	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

### **OIL CONDITION**

Visc @ 40°C

-

#### cSt 0 163

Water	%	NEG			
Silicon	ppm	0 16			
Sodium	ppm	<b>3</b>			
Potassium	ppm	0 ()			

Â				
WEA	R METALS			
Iron	ppm	0 147	 	
Copper	ppm	<b>5</b> 9	 	
Lead	ppm	0 🔘	 	
Tin	ppm	<b>○</b> <1	 	
Aluminum	ppm	01	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	02	 	
Nickel	ppm	0 0	 	
Titanium	ppm	<b>○</b> <1	 	
Silver	ppm	0 ()	 	
Manganese	ppm	<b>3</b>	 	
Vanadium	ppm	<1	 	

	DITIVES			
Calcium	ppm	<b>120</b>	 	
Magnesium	ppm	0 ()	 	
Zinc	ppm	0 47	 	
Phosphorus	ppm	0 1433	 	
Barium	ppm	01	 	
Boron	ppm	0 5	 	





## PCA

400 2ND STREET INTERNATIONAL FALLS, MN US 56649 Contact: SCOTT LINDVALL scottlindvall@boisepaper.com T: (218)285-5706 F:

# Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	PCAINT
Unique No:	10844584
Signed:	Wes Davis
Report Date:	23 Jan 2024

# CONSTRUCTION EQUIPMENT



# **GRAPHS**

 $\odot$ 

