## CONSTRUCTION EQUIPMENT



### LIEBHERR LTM1070-4.2060759 - Diesel Fuel

Sample No: LH0259056
Oil Type: {unknown}

_					
SAMPLE INFORMATION					
Sample Number		LH0259056			
Sample Date		23 Jan 2024			
Machine Hours		0			
Sample Status		ABNORMAL			
FUEL CONDITION					
Sulfur	ppm	<b>8</b>			
Visc @ 40°C	cSt	<b>2.94</b>			
CONTAMINATION					
Water	%	<b>0.078</b>			
Lead	ppm	<b>0</b>			
Nickel	ppm	<b>0</b> <1			
Aluminum	ppm	<b>0</b> <1			
Vanadium	ppm	0			
Silicon	ppm	<b>8</b>			

LIEBHERR USA CO - MOBILE AND CRAWLER CRANES 4100 CHESTNUT AVENUE NEWPORT NEWS, VA US 23607

Contact: TERENCE VANDERLENDE TERENCE.VANDERLENDE@LIEBHERR.COM

T: F:

#### Diagnosis

This is a baseline read-out on the submitted sample. Oil and filter change at the time of sampling has been noted. All metal levels are normal indicating no corrosion in the system. There is a light concentration of water present in the fuel. There is a moderate amount of visible silt present in the sample. Additive levels indicate the addition of engine oil. The condition of the fuel is acceptable for the time in service.

Depot:LIENEWUnique No:10847942Signed:Jonathan HesterReport Date:30 Jan 2024

# CONSTRUCTION EQUIPMENT





#### **GRAPHS**

