# LIEBHERR



## LIEBHERR LH110 1227-155752 - Front Right Wheel Hub

Sample No: LH0280566
Oil Type: GL-5 80W90

5							
SAMPLEINFORMATION							
Sample Number		LH0280566					
Sample Date		11 Jan 2024					
Machine Hours		507					
Oil Hours		0					
Oil Changed		Not Changd					
Sample Status		NORMAL					
A							

OIL	CONDITION			
Visc @ 40°C	cSt	<b>173</b>	 	

CON	ITAMIN/	ATION		
Water	%	NEG	 	
Silicon	ppm	<b>8</b>	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>2</b>	 	

WE!	AR META	16		
VV EA	AK ME I A			
Iron	ppm	<b>32</b>	 	
Copper	ppm	<b>0</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>O</b> <1	 	
Aluminum	ppm	<1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>O</b> <1	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	

ADD	ITIVES			
Calcium	ppm	152	 	
Magnesium	ppm	3	 	
Zinc	ppm	25	 	
Phosphorus	ppm	1273	 	
Barium	ppm	<1	 	
Boron	ppm	5	 	



### KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINTRI
Unique No: 10848675
Signed: Sean Felton
Report Date: 30 Jan 2024

# LIEBHERR







### **GRAPHS**

