LIEBHERR



LIEBHERR LH110 1227-155752 - Front Left Wheel Hub

Sample No: LH0280565
Oil Type: GL-5 80W90

<u> </u>						
SAMPLEINFORMATION						
Sample Number	LH0280565					
Sample Date	11 Jan 2024					
Machine Hours	507					
Oil Hours	0					
Oil Changed	Not Changd					
Sample Status	NORMAL					
A						

OILCO	NDITION			
Visc @ 40°C	cSt	150	 	

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	7					
Sodium	ppm	3					
Potassium	ppm	2					

WEA	R METAL	S		
Iron	ppm	33	 	
Copper	ppm	15	 	
Lead	ppm	0	 	
Tin	ppm	() <1	 	
Aluminum	ppm	() <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	

ADDI	TIVES			
Calcium	ppm	106	 	
Magnesium	ppm	2	 	
Zinc	ppm	22	 	
Phosphorus	ppm	1253	 	
Barium	ppm	2	 	
Boron	ppm	6	 	



KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:KINTRIUnique No:10848682Signed:Sean FeltonReport Date:30 Jan 2024

LIEBHERR







GRAPHS

