

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50 1216-123739 - Front Left Wheel Hub

Sample No: LH0211687

Oil Type: GEAR OIL SAE 75W90



AHLSTROM-MUNKSJO NA SPECIALTY
 PO BOX 600
 KAUKAUNA, WI
 US 54130
 Contact: JOE SEITZ
 joe.seitz@ahlstrom-munksjo.com
 T:
 F:



SAMPLE INFORMATION

Sample Number	LH0211687	LH0211645	LH0211631	LH0211617
Sample Date	31 Jan 2024	28 Mar 2023	18 Jan 2023	01 Nov 2022
Machine Hours	10743	7200	6180	5127
Oil Hours	0	0	0	0
Oil Changed	Not Changd	Not Changd	Not Changd	Not Changd
Sample Status	ABNORMAL	ABNORMAL	NORMAL	NORMAL



OIL CONDITION

Visc @ 40°C	cSt	106	136	142	144
		●	●	●	●



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	● 13	● 21	● 17	● 17
Sodium	ppm	● 9	● 15	● 10	● 12
Potassium	ppm	● <1	● 2	● 1	● 2



WEAR METALS

Iron	ppm	● 443	● 427	● 217	● 268
Copper	ppm	● 14	● 29	● 64	● 40
Lead	ppm	● 0	● 0	● <1	● <1
Tin	ppm	● 0	● 0	● <1	● <1
Aluminum	ppm	● <1	● 3	● 4	● 3
Chromium	ppm	● <1	● 2	● 1	● 1
Molybdenum	ppm	● 0	● 2	● 2	● 2
Nickel	ppm	● 0	● <1	● <1	● <1
Titanium	ppm	0	<1	<1	<1
Silver	ppm	<1	0	0	0
Manganese	ppm	● 4	● 6	● 5	● 5
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	● 97	● 236	● 206	● 251
Magnesium	ppm	● 2	● 5	● 2	● 3
Zinc	ppm	● 46	● 96	● 96	● 91
Phosphorus	ppm	● 2017	● 1982	● 1873	● 2170
Barium	ppm	● 0	● 0	● 3	● 0
Boron	ppm	● 187	● 21	● 15	● 13

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: AHLKAU
 Unique No: 10871836
 Signed: Sean Felton
 Report Date: 12 Feb 2024



GRAPHS

