



LIEBHERR LTM1130-5.1066718-1-Left Wheel Hub

Sample No: LH0259050 EP 90

Oil Type:

SAMPLE INFORMATION

Sample Number	LH0259050	 	
Sample Date	14 Feb 2024	 	
Machine Hours	0	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

...

Visc @ 40°C

OIL CONDITION

cSt

98.6

Water	%	NEG			
Silicon	ppm	9			
Sodium	ppm	02			
Potassium	ppm	02			

Ä				
WEA	R META	LS		
· · · ·		0.00		
Iron	ppm	98	 	
Copper	ppm	05	 	
Lead	ppm	0 🔘	 	
Tin	ppm	<1	 	
Aluminum	ppm	01	 	
Chromium	ppm	<mark></mark> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<mark></mark> <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

٥ **ADDITIVES** Calcium 30 ppm 2 Magnesium ppm Zinc 8 ppm 1029 Phosphorus ppm Barium 0 ppm Boron 150 ppm

LIEBHERR USA CO - MOBILE AND CRAWLER CRANES **4100 CHESTNUT AVENUE** NEWPORT NEWS, VA US 23607 Contact: TERENCE VANDERLENDE TERENCE.VANDERLENDE@LIEBHERR.COM т: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LIENEW
Unique No:	10886617
Signed:	Sean Felton
Report Date:	21 Feb 2024





Ferrous Alloys

GRAPHS

0

