

LIEBHERR LH110 1227-155752 - Front Right Wheel Hub

Sample No: LH0280577

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0280577	LH0280566				
Sample Date	20 Feb 2024	11 Jan 2024				
Machine Hours	1022	507				
Oil Hours	0	0				
Oil Changed	Changed	Not Changd				
Sample Status	NORMAL	NORMAL				
OIL CONDITION						

OIL CONDITION

Visc @ 40°C - 1

.....

cSt 0 173

Water	%	NEG	NEG		
Silicon	ppm	0 10	08		
Sodium	ppm	03	0 4		
Potassium	ppm	0	0 2		

0 173

A				
WEA WEA	R META	LS		
Iron	ppm	0 46	0 32	
Copper	ppm	0 ()	0 0	
Lead	ppm	0	0	
Tin	ppm	0	○ <1	
Aluminum	ppm	○ <1	◯ <1	
Chromium	ppm	0	0	
Molybdenum	ppm	0	0	
Nickel	ppm	0	○ <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	01	1	
Vanadium	ppm	<1	0	

	DITIVES			
Calcium	ppm	0 132	152	
Magnesium	ppm	0 🔘	3	
Zinc	ppm	0 13	25	
Phosphorus	ppm	0 1448	1273	
Barium	ppm	0	<1	
Boron	ppm	0 4	5	





KINDER MORGAN 4301 IVERSON

TRINITY, AL US 35601 Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINTRI Unique No: Signed: **Report Date:**

10898745 Wes Davis 27 Feb 2024





GRAPHS

 \odot

