LIEBHERR



LIEBHERR LH110 155976-1227 - Rear Right Wheel Hub

Sample No: LH0280579

Oil Type: GEAR OIL SAE 80W90

ā						
SAMPLE INFORMATION						
Sample Number	LH0280579	LH0280568				
Sample Date	23 Feb 2024	30 Jan 2024				
Machine Hours	995	534				
Oil Hours	0	0				
Oil Changed	Changed	Not Changd				
Sample Status	NORMAL	NORMAL				
A						

OILCO	ONDITION			
Visc @ 40°C	cSt	156	O 156	

CONTAMINATION							
Water	%	NEG	NEG				
Silicon	ppm	16	O 16				
Sodium	ppm	3	O 0				
Potassium	ppm	1	O 2				

WEA	AR META	LS		
Iron	ppm	54	4 7	
Copper	ppm	16	O 13	
Lead	ppm	0	O 0	
Tin	ppm	0	0	
Aluminum	ppm	2	O 2	
Chromium	ppm	○ <1	O <1	
Molybdenum	ppm	0	O 0	
Nickel	ppm	○ <1	0	
Titanium	ppm	<1	O 0	
Silver	ppm	0	0	
Manganese	ppm	2	O <1	
Vanadium	ppm	0	0	

variaulum	ppiii	U	U			
ADDITIVES						
Calcium	ppm	112	O 114			
Magnesium	ppm	2	O <1			
Zinc	ppm	26	O 6			
Phosphorus	ppm	1526	1240			
Barium	ppm	0	6			
Boron	ppm	13	17			



KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:KINTRIUnique No:10902894Signed:Wes DavisReport Date:01 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

