

LIEBHERR L526 068228-1753 - Rear Left Wheel Hub

Sample No: LH0268758

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLE INFORMATION

Sample Number	LH0268758	 	
Sample Date	14 Mar 2024	 	
Machine Hours	705	 	
Oil Hours	705	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

0 0

. .

OIL CONDITION

Visc @ 40°C

cSt 🔘 186

Water	%	NEG		
Silicon	ppm	0 11		
Sodium	ppm	0 2		
Potassium	ppm	0 2		

👾 WEA	R META	LS		
Iron	ppm	0 166	 	
-	ppm	-		
Copper	ppm	0 (
Lead	ppm	0 (
Tin	ppm	0	 	
Aluminum	ppm	0 2	 	
Chromium	ppm	0 2	 	
Molybdenum	ppm	0 🔘	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	03	 	
Vanadium	ppm	0	 	

ADDITIVES

Calcium	ppm	31	 	
Magnesium	ppm	0 2	 	
Zinc	ppm	5 3	 	
Phosphorus	ppm	0 2001	 	
Barium	ppm	○ <1	 	
Boron	ppm	○ <1	 	





LIEBHERR EQUIPMENT SOURCE

8200 FAYETTEVILLE ROAD RALEIGH, NC US 27603 Contact: Timothy Bailey timothy.bailey@liebherr.com T: F: (919)329-0084

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LIEBHERRNC
Unique No:	10928642
Signed:	Wes Davis
Report Date:	18 Mar 2024

Submitted By: TAYLOR BLALOCK





GRAPHS

0

