



## 135024 - Grease

Sample No:LH0264486Oil Type:NUG 12

=

U Samp	ole Infor	mation		
Sample Number		LH0264486	 	
Sample Date		25 Mar 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		SEVERE	 	
24 C				
Conto	aminatio	on		
Water	%	NEG	 	
Silicon	ppm	<b>0</b> 385	 	
Sodium	ppm	0 43	 	
Potassium	ppm	<b>58</b>	 	
*				
Wea	r Metals	5		
PQ		11008	 	
Iron	ppm	<b>3387</b>	 	
Copper	ppm	8	 	
Lead	ppm	0 2	 	

## LIEBHERR NENZING CRANE CO.

7075 BENNINGTON ST HOUSTON, TX US 77028 Contact: JONATHAN KAY JOHNATHAN.KEY@LIEBHERR.COM T: F: (713)636-4051

## Diagnosis

Re-sample to verify the actual grease condition. Purge old grease if still abnormal and monitor the trend of iron level. Please submit a sample of the new (unused) oil to establish a baseline.The iron level is abnormal. Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. {not applicable}

Leau	ppm	<b>2</b>					
Tin	ppm	<b>○</b> <1					
Aluminum	ppm	<u> </u>					
Chromium	ppm	<b>4</b> 1					
Molybdenum	ppm	17					
Nickel	ppm	0 6					
Titanium	ppm	<mark>()</mark> 16					
Silver	ppm	08					
Manganese	ppm	33					
Vanadium	ppm	<1					
Additives							
Calcium	maa	1254					

Calcium	ppm	1254	 	
Magnesium	ppm	81	 	
Zinc	ppm	3420	 	
Phosphorus	ppm	1910	 	
Barium	ppm	0	 	
Boron	ppm	414	 	

 Depot:
 LIEBHERRNZ

 Unique No:
 10942496

 Signed:
 Doug Bogart

 Report Date:
 11 Apr 2024

 Contact/Location: JONATHAN KAY - LIEBHERRNZ

## **LEBHERR** CONSTRUCTION EQUIPMENT



Ø

