# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH80M 1218-157090 - Rear Right Wheel Hub

Sample No: LH0282901

Oil Type: GEAR OIL SAE 80W90

5				
SAMI	PLE INFO	RMATION		
Sample Number		LH0282901	 	
Sample Date		19 Mar 2024	 	
Machine Hours		545	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OILC	ONDITIO	N		
Visc @ 40°C	cSt	<b>139</b>	 	
CONT	'AMINAT	ION		

CONTAMINATION						
Water	%	NEG				
Silicon	ppm	<b>10</b>				
Sodium	ppm	<b>2</b>				
Potassium	ppm	<b>O</b> <1				

WEA	R META	LS		
Iron	ppm	<b>34</b>	 	
Copper	ppm	<b>10</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b></b> <1	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	<b>()</b> <1	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<b>()</b> <1	 	
Vanadium	ppm	<1	 	

ADDITIVES						
Calcium	ppm	<b>139</b>				
Magnesium	ppm	<b>○</b> <1				
Zinc	ppm	<b>19</b>				
Phosphorus	ppm	<b>1382</b>				
Barium	ppm	<b>0</b>				
Boron	ppm	<b>3</b>				



#### KINDER MORGAN

4301 IVERSON TRINITY, AL US 35601

Contact: RICKY JOHNSON ricky\_johnson@kindermorgan.com

Т:

F: (256)355-5250

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINTRI
Unique No: 10950652
Signed: Wes Davis
Report Date: 28 Mar 2024

## LIEBHERR

### CONSTRUCTION EQUIPMENT





#### **GRAPHS**

