# CONSTRUCTION EQUIPMENT

## LIEBHERR LH50 1216-130389 - Front Left Wheel Hub

Sample No: LH0217921

Oil Type: GEAR OIL SAE 80W90

### **SAMPLE INFORMATION**

Sample Number	LH0217921	LH0217909	LH0217897	LH0200598
Sample Date	19 Mar 2024	14 Jun 2023	18 Aug 2022	10 Feb 2022
Machine Hours	3007	1990	997	4749
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL
OIL CONDI	<b>ION</b>			
Visc @ 40°C cSt	0 127	0 144	0 145	0 156
<b>**</b>				

CONTAMINATION						
Water	%	NEG	NEG	NEG	NEG	
Silicon	ppm	06	0 12	0 11	23	
Sodium	ppm	07	0 10	0 4	○ 5	
Potassium	ppm	04	08	02	02	

Ä					
WEAI	R METALS				
Iron	ppm	0 142	180	0 77	0 143
Copper	ppm	0 13	0 12	0 14	0 18
Lead	ppm	0	2	0	○ <1
Tin	ppm	0 ()	01	0	○ <1
Aluminum	ppm	<b>○</b> <1	3	2	3
Chromium	ppm	<mark>○</mark> <1	○ <1	○ <1	○ <1
Molybdenum	ppm	0	○ <1	2	<b>5</b>
Nickel	ppm	○ <1	01	○ <1	○ <1
Titanium	ppm	<1	<1	0	<1
Silver	ppm	0	<1	<1	0
Manganese	ppm	02	3	01	2
Vanadium	ppm	0	<1	0	0

0 **ADDITIVES** Calcium 0 40 ppm 0 59 83 186 08 Magnesium 8 03 3 ppm 0 33 Zinc 0 24 031 071 ppm 0 848 Phosphorus ppm 0 808 0 1017 0 1721 Barium 0 0 ppm  $\bigcirc 0$  $\bigcirc 0$ Boron ppm 0 02 3  $\bigcirc 4$ 





#### AMERICAN STATE EQUIPMENT CO.

2400 NORTH 14TH AVENUE WAUSAU, WI US 54401 Contact: CHRIS BARTNIK cbartnik@amstate.com T: (715)675-6900 F: (715)675-9748

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LEC0
Unique No:	10955
Signed:	Wes D
Report Date:	02 Ap





GRAPHS

 $\odot$ 

