

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 1253-143895 - Front Right Wheel Hub

Sample No: LH0276323

Oil Type: {unknown}



TRAM CONSTRUCTION
 9279 E KY 8
 GARRISON, KY
 US 41141
 Contact: Service Manager

T:
 F:



Sample Information

Sample Number	LH0276323	---	---	---
Sample Date	17 Apr 2024	---	---	---
Machine Hours	974	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



Oil Condition

Visc @ 40°C	cSt	● 92.6	---	---	---
-------------	-----	--------	-----	-----	-----



Contamination

Water	%	NEG	---	---	---
Silicon	ppm	● 3	---	---	---
Sodium	ppm	● 8	---	---	---
Potassium	ppm	● 0	---	---	---



Wear Metals

Iron	ppm	● 29	---	---	---
Copper	ppm	● 11	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	● 0	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	● 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



Additives

Calcium	ppm	1613	---	---	---
Magnesium	ppm	6	---	---	---
Zinc	ppm	653	---	---	---
Phosphorus	ppm	777	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	49	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: TRAGARLH
Unique No: 11004463
Signed: Wes Davis
Report Date: 30 Apr 2024



Graphs

