CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 107256-1216 - Front Right Wheel Hub

Sample No: LH06169232

Oil Type: GEAR OIL SAE 80W90

Sample Information

Sample Number	LH06169232	LH05510127	LH05170952	LHMC102452				
Sample Date	02 May 2024	03 Apr 2022	30 Jan 2021	05 Jan 2020				
Machine Hours	3993	2974	1987	1017				
Oil Hours	0	0	0	0				
Oil Changed	Changed	Changed	N/A	Changed				
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL				
Oil Condition								
Visc @ 40°C cSt	181	185	188	187				

Con	taminati	on			
Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	1 3	0 14	0 18	5
Sodium	ppm	0 14	0 13	0 12	6
Potassium	ppm	0	0	◯ <1	0

Ä					
Wea Wea	r Metals				
Iron	ppm	0 40	◯ 43	0 47	26
Copper	ppm	07	07	9	0 11
Lead	ppm	0 (0	◯ <1	0
Tin	ppm	0 (○ <1	0	0
Aluminum	ppm	○ <1	01	0	○ <1
Chromium	ppm	0 ()	○ <1	◯ <1	○ <1
Molybdenum	ppm	0 (◯ <1	◯ <1	0
Nickel	ppm	0 (○ <1	0	○ <1
Titanium	ppm	0	<1	<1	0
Silver	ppm	0	0	0	0
Manganese	ppm	○ <1	◯ <1	0 1	○ <1
Vanadium	ppm	0	0	0	0

٥ **Additives** Calcium ppm 0 21 33 38 0 44 Magnesium 0 0 ppm 01 01 23 Zinc 0 21 0 15 0 20 ppm Phosphorus 0 2266 0 2225 ppm 0 2171 0 1938 Barium 0 0 ppm 0 0 Boron ppm 0 03 3 8



DIEHL AND NUEMAIER

5466 NORWAY GROVE SCHOOL RD DE FOREST, WI US 53532 Contact: ELLIOT DIEHL diehlneumaier@yahoo.com T: (608)846-4824 F: (608)846-2077

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:DIEDEFUnique No:11009951Signed:Jonathan HesterReport Date:08 May 2024Contact/Location:ELLIOT DIEHL - DIEDEF





Ø

Graphs



Report Id: DIEDEF [WUSCAR] 06169232 (Generated: 05/11/2024 02:55:45) Rev: 1