LIEBHERR

CONSTRUCTION EQUIPMENT



[[US GYPSUM]] LIEBHERR L566 071890-1758 - Rear Different

Sample No: LH0217108

Oil Type: GEAR OIL SAE 80W90

_				
□ Sam	ple Infor	mation		
Sample Number		LH0217108	 	
Sample Date		23 Apr 2024	 	
Machine Hours		3662	 	
Oil Hours		1500	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
<u> </u>		, , , , , , , , , , , , , , , , , , , ,		
Oilc	ondition			
Visc @ 40°C	cSt	189	 	
Cont	aminatio			
Water	%	NEG	 	
Silicon	ppm	9	 	
Sodium	ppm	 <1	 	
Potassium	ppm	2	 	
© Wed	ır Metals			
- AAGG	ir metais			
Iron	ppm	185	 	
Copper	ppm	208	 	
Lead	ppm	○ <1	 	
Tin	ppm	O 6	 	
Aluminum	ppm	2	 	
Chromium	ppm	1	 	
Molybdenum	ppm	() <1	 	
Nickel	ppm	3	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	9	 	
Vanadium	ppm	<1	 	
Add	itives			
Calcium	ppm	24	 	
Magnesium	ppm	2	 	
Zinc	ppm	55	 	
- ·				



NUECES POWER EQUIPMENT

7333 MONROE RD HOUSTON, TX US 77061

Contact: Keith Frischenmeyer

keith@npetex.com T: (713)247-0066 F: (713)636-4039

Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEBHERRTX
Unique No: 11021979
Signed: Sean Felton
Report Date: 14 May 2024

2630

2

 \bigcirc 0

Phosphorus

Barium

Boron

ppm

ppm

ppm







Graphs

