## CONSTRUCTION EQUIPMENT



### LIEBHERR LRT 1100-2.1 Bigge LRT (S/N 044808) - Front Axle

Sample No: LH0257765

Oil Type: LIEBHERR GEAR BASIC 90 LS

_				
Sami	ple Infor	mation		
	<b>7.0</b>			
Sample Number		LH0257765	 	
Sample Date		21 May 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
Oil Co	ondition			
Visc @ 40°C	cSt	<b>184</b>	 	
V13C @ +0 C	COL	0 104		
Cont	aminatio	on		
Water	%	NEG	 	
Silicon	ppm	<b>5</b>	 	
Sodium	ppm	0 2	 	
Potassium	ppm	0	 	
	PPIII			
<b>Wea</b>				
Wea	r Metals	•		
Iron	ppm	<b>5</b>	 	
Copper	ppm	<b>6</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b> 0	 	
Aluminum	ppm	<b>0</b> 0	 	
Chromium	ppm	<b>0</b> 0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>0</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	O <1	 	
Vanadium	ppm	0	 	
	Ph			
Addi				
Addi	tives			
Calcium	ppm	<b>23</b>	 	
Magnesium	ppm	<b>0</b> 0	 	
Zinc	ppm	<b>6</b>	 	
Phosphorus	ppm	① 1157	 	
Barium	ppm	0	 	
Boron	ppm	○ <1	 	
DOIGH	PPIII	<u> </u>		

#### LIEBHERR CRANE INC

7075 BENNINGTON ST HOUSTON, TX US 77028

Contact: RANDY BLUM randy.blum@liebherr.com

T: (713)636-4000 F: (713)636-4039

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEHOUUnique No:11044857Signed:Sean FeltonReport Date:24 May 2024

Submitted By: ALEXANDER BUECH

# CONSTRUCTION EQUIPMENT





### **Graphs**

