

LIEBHERR PR766 023058-1681 - Hydraulic System

Sample No: LH0273669

Oil Type: LIEBHERR HYDRAULIC HVI

Sample Information

Sample Number	LH0273669	 	
Sample Date	15 May 2024	 	
Machine Hours	946	 	
Oil Hours	946	 	
Oil Changed	Not Changd	 	
Sample Status	NORMAL	 	

0 44.0

0.91

Oil Condition Visc @ 40°C cSt

Acid Number (AN) mg KOH/g -

Conta	Contamination					
Water	%	NEG				
Particles >4µm		5722				
Particles >6µm		0 426				
Particles >14µm		50				
ISO 4406:1999 (c)		20/16/13				
Silicon	ppm	04				
Sodium	ppm	04				
Potassium	ppm	0				

Wear Metals

Iron	ppm	07	 	
Copper	ppm	07	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	○ <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 ()	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

0

Additives Calcium ppm 0818 Magnesium ppm **○** <1 Zinc 0 538 ppm Phosphorus 0 504 ppm Barium 0 🔘 ppm Boron ppm 0





RECO EQUIPMENT INC

10461 GRAND RIVER RD BRIGHTON, MI US 48116 Contact: MATT VISEL MVISEL@RECOEQUIP.COM T: (810)299-1731 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot: RECBRILH Unique No: 11047141 Signed: Wes Davis **Report Date:** 28 May 2024 Contact/Location: MATT VISEL - RECBRILH

LEBHERR CONSTRUCTION EQUIPMENT



Graphs

Ö


