

## LIEBHERR L538 055489-1559 - Front Left Wheel Hub

Sample No: LH0273548

Oil Type: LIEBHERR GEAR BASIC 90 LS

## **Sample Information**

Sample Number	LH0273548	 	
Sample Date	08 May 2024	 	
Machine Hours	4169	 	
Oil Hours	4169	 	
Oil Changed	N/A	 	
Sample Status	NORMAL	 	

## **Oil Condition**

Visc @ 40°C

Boron

# cSt

0 190

Conto	Contamination					
Water	%	NEG				
Silicon	ppm	<b>0</b> 19				
Sodium	ppm	02				
Potassium	ppm	01				

#### $\bigcirc$ Wear Metals Iron ppm 0 128 Copper ppm ○ <1 Lead 0 <1 ppm Tin ppm <1 Aluminum ppm 02 Chromium ppm 02 Molybdenum 0 ( ppm Nickel ppm ○ <1 Titanium ppm <1 Silver 0 ppm Manganese 05 ppm Vanadium ppm Ω

0 **Additives** Calcium ppm 33 Magnesium ppm 03 Zinc 0 61 ppm Phosphorus ppm 0 2120 Barium 0 ppm



# CHESAPEAKE BAY

2201 MINGEE DR. HAMPTON, VA US 23661 Contact: SERVICE MANAGER

T: (757)827-4778 F: (757)827-0978

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	CHEHAMLH			
Unique No:	11075613			
Signed:	Wes Davis			
Report Date:	14 Jun 2024			
Location: SERVICE MANAGER CHEHAMI				

0 10

ppm





# Graphs

### Ferrous Alloys

