LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-146764 - Diesel Engine

Sample No: LH0276518

Oil Type: PETRO CANADA DURON UHP 5W30

Sample Information						
Sample Number	LH0276518	LH0276506	LH0276509			
Sample Date	30 May 2024	01 Mar 2024	08 Feb 2024			
Machine Hours	1548	500	1019			
Oil Hours	0	0	0			
Oil Changed	Changed	Changed	Changed			
Sample Status	NORMAL	ABNORMAL	ATTENTION			
X						

Oil Co	ndition				
Visc @ 100°C	cSt	10.9	O 11.4	11.2	
Base Number (BN)	mg KOH/g	8.5	O 5.2	7.8	
Oxidation (PA)	%	86	191	101	

Contamination						
Water	%	NEG	NEG	NEG		
Soot %	%	0.1	0.1	0.1		
Nitration (PA)	%	83	98	83		
Sulfation (PA)	%	55	104	62		
Glycol	%	NEG	NEG	NEG		
Fuel	%	<1.0	<1.0	1.4		
Silicon	ppm	6	10	7		
Sodium	ppm	3	0	O 0		
Potassium	ppm	3	5	 <1		

(2)					
Wea	r Metals				
Iron	ppm	0 <1	O 11	6	
Copper	ppm	13	O 244	O 72	
Lead	ppm	0	3	O 1	
Tin	ppm	0	1	O <1	
Aluminum	ppm	0 <1	3	O 1	
Chromium	ppm	0	O <1	O <1	
Molybdenum	ppm	43	45	47	
Nickel	ppm	0 <1	0	O 0	
Titanium	ppm	0	0	0	
Silver	ppm	0	O 0	0	
Manganese	ppm	1	O <1	O <1	
Vanadium	ppm	0	0	0	

Additives						
Calcium	ppm	1358	O 1309	O 1315		
Magnesium	ppm	868	○ 889	868		
Zinc	ppm	834	○ 857	864		
Phosphorus	ppm	691	O 699	O 634		
Barium	ppm	 <1	29	6		
Boron	ppm	107	O 91	○ 86		



TRAM CONSTRUCTION 9279 E KY 8 GARRISON, KY

US 41141

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: TRAGARLH
Unique No: 11076921
Signed: Don Baldridge
Report Date: 17 Jun 2024
Submitted By: ?

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

