**CONSTRUCTION EQUIPMENT** 

## LIEBHERR LH40M 1215-149851 - Rear Left Wheel Hub

Sample No: LH0273634

**Oil Condition** 

Oil Type: LIEBHERR GEAR BASIC 90 LS

5					
Sample Information					
Sample Number	LH0273634				
Sample Date	14 May 2024				
Machine Hours	549				
Oil Hours	549				
Oil Changed	Not Changd				
Sample Status	NORMAL				

LAGRANGE, KY
US 40031
Contact: Service Manager
T:

F:

2615 KY-146

VISC @ 40 C	COL	130				
Contamination						
Water	%	NEG				
Silicon	ppm	<b>13</b>				
Sodium	ppm	<b>7</b>				
Potassium	ppm	<b>2</b>				

Diagnosis
Resample at the next service interval
to monitor.All component wear rates
are normal. There is no indication of
any contamination in the oil. The
condition of the oil is acceptable for
the time in service.

(O) Was				
Wed	ır Metals	•		
Iron	ppm	<b>64</b>	 	
Copper	ppm	<b>20</b>	 	
Lead	ppm	<1	 	
Tin	ppm	<1	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	

variaululli	ppiii	U			
Additives					
Calcium	ppm	<b>150</b>			
Magnesium	ppm	<b>2</b>			
Zinc	ppm	<b>43</b>			
Phosphorus	ppm	1422			
Barium	ppm	<b>4</b>			
Boron	ppm	<b>39</b>			

Depot: STALAGKY Unique No: 11087986 Signed: Wes Davis Report Date: 20 Jun 2024 Submitted By: ?

STAINLESS STEL MIDWEST

## CONSTRUCTION EQUIPMENT





## **Graphs**

