

LIEBHERR L586 1334-49308 - Splitter Box

Sample No: LH0172269

Oil Type: LIEBHERR GEAR BASIC 90 LS

Sample Information

Sample Number		LH0172269	LH0172256	LH0172243				
Sample Date		15 Feb 2024	19 Jun 2023	12 Aug 2022				
Machine Hours		6112	5000	4006				
Oil Hours		0	0	0				
Oil Changed		Changed	N/A	Changed				
Sample Status		NORMAL	NORMAL	NORMAL				
Oil Condition								
Visc @ 40°C	cSt	0 152	0 150	0 195				

Contamination						
Water	%	NEG	NEG	NEG		
Silicon	ppm	0 2	○ <1	02		
Sodium	ppm	01	0	04		
Potassium	ppm	0	01	0		

i a					
Wee Wee	ar Metals	S			
Iron	ppm	0 12	0 16	○ 59	
Copper	ppm	0 2	0 2	03	
Lead	ppm	0	◯ <1	◯ <1	
Tin	ppm	0	◯ <1	◯ <1	
Aluminum	ppm	0	0	0 1	
Chromium	ppm	0 ()	0	○ <1	
Molybdenum	ppm	04	5	9	
Nickel	ppm	0 2	0 4	26	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	0 🔘	<1	3	
Vanadium	ppm	0	0	0	

Additive

Calcium	ppm	9 9	167	65	
Magnesium	ppm	0 🔘	3	7	
Zinc	ppm	245	309	310	
Phosphorus	ppm	0 2137	2078	2360	
Barium	ppm	0 🔘	0	0	
Boron	ppm	01	0	3	





STARK PAVING

12845 BURLEIGH ROAD BROOKFIELD, WI US 53005 Contact: DANIEL MIGAAZ danm@starkcorp.us T: (414)507-5987 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:STAUnique No:1112Signed:WesReport Date:20 J

STABROWI 11129889 Wes Davis 20 Jul 2024 Submitted By: ?





Ø

Graphs

