



# LIEBHERR LH40M 098208 - Rear Left Wheel Hub

Sample No: LH

Oil Type: GEAR OIL SAE 80W90

## **INFORMATION SUR L'ÉCHANTILLON**

0 191

Numéro d'échant.	LH	 
Date d'échant.	29 Jun 2023	 
Heures de la Machine	6242	 
Heures de l'huile	135	 
Huile changée	Not Changd	 
Statut de l'echant.	NORMAL	 

🌒 ÉT

#### ÉTAT D'HUILE

Visc 40°C

# cSt

	ITAMINA	TION		
Silicium	ppm	04	 	
Sodium	ppm	0 9	 	
Potassium	ppm	<b>○</b> <1	 	

Ä				
Mé	raux d'u	SURE		
Fer	ppm	<b>5</b> 3	 	
Cuivre	ppm	0 52	 	
Plomb	ppm	01	 	
Étain	ppm	0 🔘	 	
Aluminium	ppm	◯ <1	 	
Chrome	ppm	<b>○</b> <1	 	
Molybdène	ppm	0 🔘	 	
Nickel	ppm	<b>○</b> <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	01	 	
Vanadium	maa	0	 	

#### 0 **ADDITIFS** Calcium 0 12 ppm Magnésium 01 ppm Zinc 0 39 ppm Phosphore 0 2304 ppm Baryum ppm ◯ <1 Bore 02 ppm



#### LIEBHERR CANADA LTEE

444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7 Contact: Luc Trottier luc.trottier@liebherr.com T: F: (418)276-9844

### Diagnostic

Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	LBADOL
Unique No:	5605115
Signed:	Kevin Marson
Report Date:	20 Jul 2023





GRAPHS

 $\odot$ 



ID du rapport: LBADOL [WCAMIS] 02568069 (Generated: 07/20/2023 07:29:53) Rev: 2

Submitted By: Olivier Galimi