



### LIEBHERR LH60M 145111-1217 - Splitter Box

Sample No: LH0266081

Oil Type: GEAR OIL SAE 80W90



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0266081	LH0261405	---	---
Date d'échant.	20 Jun 2023	27 Apr 2023	---	---
Heures de la Machine	1188	558	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---

#### RAM IRON AND METAL

60 Ashwarren Road  
 TORONTO, ON  
 CA M3J 1Z5  
 Contact: PETER RACCO  
 PETER@RAMIRON.COM  
 T: (416)630-4545  
 F: (416)630-5258



#### ÉTAT D'HUILE

Visc 40°C	cSt	● 121	● 191	---	---
-----------	-----	-------	-------	-----	-----



#### CONTAMINATION

Silicium	ppm	● 1	● 1	---	---
Sodium	ppm	● 2	● 3	---	---
Potassium	ppm	● 1	● 2	---	---



#### MÉTAUX D'USURE

Fer	ppm	● 25	● 20	---	---
Cuivre	ppm	● <1	● <1	---	---
Plomb	ppm	● 0	● <1	---	---
Étain	ppm	● 0	● 0	---	---
Aluminium	ppm	● <1	● <1	---	---
Chrome	ppm	● <1	● 0	---	---
Molybdène	ppm	● 0	● 0	---	---
Nickel	ppm	● <1	● <1	---	---
Titane	ppm	● 0	● 0	---	---
Argent	ppm	● 0	● 0	---	---
Manganèse	ppm	● <1	● 1	---	---
Vanadium	ppm	● 0	● 0	---	---



#### ADDITIFS

Calcium	ppm	● 13	● 14	---	---
Magnésium	ppm	● 2	● 2	---	---
Zinc	ppm	● 21	● 17	---	---
Phosphore	ppm	● 1497	● 1633	---	---
Baryum	ppm	● 0	● 0	---	---
Bore	ppm	● 190	● 1	---	---

#### Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: RAMTOR  
 Unique No: 5605929  
 Signed: Wes Davis  
 Report Date: 10 Jul 2023



### GRAPHS

