

LIEBHERR

CONSTRUCTION EQUIPMENT



[(374942)] LIEBHERR TA230 137792-1513 - Transmission (Au

Sample No: LH0265835

Oil Type: DEXRON III



PRIESTLY DEMOLITION INC
3200 LLOYDTOWN-AURORA RD.
KING, ON
CA L7B 0G3
Contact: Service Manager

T:
F:



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0265835	---	---	---
Date d'échant.	22 Jun 2023	---	---	---
Heures de la Machine	1017	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Not Chngd	---	---	---
Statut de l'échant.	NORMAL	---	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	● 34.9	---	---	---
-----------	-----	--------	-----	-----	-----



CONTAMINATION

Silicium	ppm	● 5	---	---	---
Sodium	ppm	● 4	---	---	---
Potassium	ppm	● 2	---	---	---



MÉTAUX D'USURE

Fer	ppm	● 19	---	---	---
Cuivre	ppm	● 7	---	---	---
Plomb	ppm	● <1	---	---	---
Étain	ppm	● 0	---	---	---
Aluminium	ppm	● <1	---	---	---
Chrome	ppm	● 0	---	---	---
Molybdène	ppm	● 0	---	---	---
Nickel	ppm	● 0	---	---	---
Titane	ppm	● 0	---	---	---
Argent	ppm	● 0	---	---	---
Manganèse	ppm	● <1	---	---	---
Vanadium	ppm	● 0	---	---	---



ADDITIFS

Calcium	ppm	● 152	---	---	---
Magnésium	ppm	● 2	---	---	---
Zinc	ppm	● 12	---	---	---
Phosphore	ppm	● 302	---	---	---
Baryum	ppm	● 2	---	---	---
Bore	ppm	● 125	---	---	---

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: PRI320KIN
Unique No: 5606829
Signed: Wes Davis
Report Date: 13 Jul 2023



GRAPHS

